Maryland Historical Trust Maryland Inventory of Historic Properties Form Survey No. B-4746 1. Name

105-121 South Regester Street

2. Location

Historic and / common

street & number	105 - 121 South	Regester Street	
city, town	Baltimore		
state & zip code	Maryland 212	31 county	

3. Classification

Categorydistrict X building(s)structuresiteobject	Ownership public X private both Public Acquisition in process	X occupiedunoccupiedwork in progress Accessible X yes: restricted	Present Useagriculturecommercialeducationalentertainmentgovernment	museum park X private residence religious scientific
_ •	being considered not applicable	yes: unrestricted no	industrial military	transportation other:

4. Owner of Property

name	
street & number	telephone
city, town	state & zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Baltimore City Land Records				liber	
street & number Clarence Mitchell Courthou		Clarence Mitchell Courthouse			folio
city, town	Baltimore		State	Maryland	

6. Representation in Existing Historical Surveys

title				
date	federal	state	county	local
depository for survey records				
city, town	state & zip code			

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. B-4746

7. Description

Condition		Check One	Check One
excellent _x good fair	deteriorated ruins unexposed	${X}$ unaltered altered	X original sitemoved: date of move:

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The east side of the 100 block of S. Regester St. is comprised of a long row of two-story-and-attic houses, one of which has been enlarged to a full three story house with a Renaissance-Revival style cornice. One house, 105, was originally built as a three story, early Italianate-style house.

105 S. Regester St. is a three story early Italianate-style house. With its north side wooden addition it is 19'6" wide and occupies a lot only 30' deep. The house is constructed in running bond that was always painted. The shed roof is capped by a wooden cornice consisting of a deeply projecting crown molding supported by a row of block modillions set against a shallow, plain frieze area. Door and window openings have segmentally arched brick lintels and wood sills. None of the original 2/2 sash survives and the window openings are filled with 1/1 replacement sash. The doorway has a single-light transom and a modern replacement door. The house sits on a high basement, lit by a double-hung sash. The entrance is reached by six metal steps, set parallel to the facade.

107 – 121 S. Regester St. is a group of eight, two-bay-wide, two-story-and-attic brick houses typical of a popular type of Baltimore rowhouse built in the late 1840s and 1850s to serve the city's growing working class population. The lower-pitched gable roof allowed for a more spacious upper story, which now could be lit by small rectangular windows at both the front and rear of the house, instead of the earlier dormer windows. Despite its practical nature, this new feature had its roots in a stylistic change in Baltimore's fashionable housing, the small "attic" windows being an important part of the façade design of much larger town mansions being built in the new Greek Revival style.

The houses are two-and-a-half stories in height, 14' wide, and occupy lots 70' deep. Each house has a one-story brick rear kitchen addition somewhat narrower than the house. Because early house lots in Baltimore were laid out back to back, without rear service alleys, the only street entrance to the backyard is through the flat-linteled sallyport located in the center of each pair. The houses are constructed in running bond, and were always painted, but some have been covered with formstone. The low-pitched gable roof has a simple corbelled brick cornice. The roofs are covered with modern asphalt shingles overtop the original cedar shakes. A double, hooded chimney located at the peak of the gable roof, serves both the front and rear rooms. Each house also has a chimney at the rear of the kitchen addition.

Continuation sheet

All of the first and second floor door and window openings have segmentally arched brick lintels. The narrow attic windows have no lintels, except for 121, which has third floor segmentally arched brick lintels. All of the sills are wood. None of the original 6/6 or 4/4 sash survives and the window openings are filled with 1/1 replacement sash. All of the original doors have been replaced with a variety of replacement door types set beneath single light transoms, many of which have been covered with aluminum siding or boarded over. The houses sit on low basements, lit by a single-light sash. The entrances are reached by two or three concrete, brick, or wooden steps.

The houses are two rooms deep, with the front room being entered directly from the front door. The front and back rooms of the first floor are separated by a wide opening, with the tightly winding, narrow stairs set in the rear room, in the space between the partition wall and the fireplace. There are two bedrooms on the second floor of the main part of the house, each with a fireplace. The third floor attic rooms have low sloping ceilings, with a maximum ceiling height of about seven feet at the peak of the gable sloping down to about four feet at the front and rear of the house. The one-story rear addition served as the kitchen, with its own cooking fireplace.

Maryland	Historical	Trust		
aryland	Inventory	of Historic	Properties	Form

Survey No. B-4746

8. Significance

Period	Area of significance	check one & justify		
prehistoric 1400-1499 1500-1599 1600-1699 1700-1799 X 1800-1899 1900	archeology-prehistoric archeology-historic agriculture X architecture art commerce communications	X community planningconservationeconomicseducationengineeringexplorationindustryinvention	landscape architecture law literature military music philosophy politics/government	religion science sculpture X social/ humanitarian theatre transportation other: specify
Specific dates c	1845 - 1855		Builder/Architect	

Prepare both a summary paragraph of significance and a general statement of history and support.

This row of houses is significant as being representative of a large group of such houses built in the 1840s and 1850s to accommodate the growing labor force centered around the Baltimore waterfront and the city's fledgling industrial areas, such as Canton and southwest Baltimore. Although showing stylistic influences from Greek Revival style buildings constructed in Baltimore in the 1830s and 1840s (in the proportions of the attic windows, the chaste exterior details, and the double parlor floor plan), the outstanding feature of these houses is their extreme simplicity of design and detailing. They are practical adaptations of a current mode of building, designed to meet the need for efficient, low-cost housing for a growing working class community. The floor plan is essentially the same as that of the earlier Federal-style two-and-a-half story houses, but the opening between the two rooms is wider, reflecting popular Greek Revival tastes. The increase in height of the third story (from a dormer story to an attic story) allowed the third story to be divided into two separate rooms, in place of the one open room of the dormer story, thus providing welcome additional private living space to large families or those who had to take in boarders. The houses do not differ markedly from similar two-story-and-attic houses built on nearby main streets—they are simply somewhat narrower versions priced to serve less affluent residents of the old walking city.

These particular houses were built at a time when Fells Point was already an important ship building center for the growing town of Baltimore and was beginning to have a few small factories. Early occupants included people involved in the maritime trades, small-scale craftsmen, and laborers who made their homes in the smaller-scale and more affordable housing located on the small "alley" streets of Fells Point. Until about 1850 Regester Street was known as Argyle Alley and its occupants were racially mixed.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Survey No. B-4746

9. Major Bibliographic References

Mary Ellen Hayward and Charles Belfoure, *The Baltimore Rowhouse* (New York: Princeton Architectural Press, 1999)

10. Geographic Data

Acreage of nominated property

Quadrangle name

Verbal boundary description and justification


11. Form Prepared by

name / title D	r. Mary Ellen Hayward			
Organization 7	The Alley House Project	date June	2000	
street & number	1306 Carrollton Ave.	telephone		
city, town	Baltimore	state & zip code	Maryland	21204


The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotate Maryland, Article 41, section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement ϵ rights.

Return to: DHCP/DHCD Maryland Historical Trust 100 Community Place Crownsville MD 21032-2023



B-4746 105-121 S. Regester Street Block 1744, Lots 072-080 Baltimore City Baltimore East Quad.





105 5. Tagester

B-1746 105-1215 Requirer St. Stronger ... O. Belgonie 11197

MD SHDO

1/1

173402 021 N N N 27



B-4786
165-171 S. Regester St
BALTO, MD
C. Belfowe =
11/47
1/4



109-121 S. Tagester 105-121 S. Tagester St. BATO. MD C. Delfonte 11/97 3/4

18D [15]402 0211 H H H 30



117 S. RepESTET

B-4746 117 S. Regioner St BACD. HU C. Belfowe : 11/47 4/4

43402 9211 N R X